



Core4 Services  
9a/62 Bishop St,  
Kelvin Grove QLD 4059

13<sup>th</sup> Jun 2024  
Job No. S5466

## Concrete Remedial Works - 85 Deakin St, Kangaroo Point

### Introduction & Background

Design Sirs has been engaged by Core4 Services to conduct a structural assessment of concrete cancer to the ground floor slabs and provide recommended repairs to same. Concerns had been raised after concrete cracking & spalling was noted below the slab during pool re-fit works.

The structure is a 4-storey multi-residential dwelling with 1 basement below, it has been constructed with suspended slab floors which are supported by block masonry walls. The ground floor slab is supported on band beams & concrete columns below. Built in approx. 1995, the building is approximately 29 years old.

The pool retrofit works completed on-site between Nov.-Dec. 2023 were understood to have been related to drainage issues around the slab & that large amounts of water was ponding/ leaking to slab area around the pool. Works have been finished & drainage issues remediated.

### Site Inspection

Design Sirs attended site on 31<sup>st</sup> March 2023 with Core4 Services, weather at the time of inspection was fine & sunny. The scope of the investigation was limited to a visual inspection of the ground floor slab, with a specific focus on the slab region as indicated in figure 1 below. The slab outside the area shaded green was found to be in good condition, with negligible indication of concrete cancer/ deterioration.

Appendix A provides a photographic record of defects & inspection, Appendix B provides indicative site plan for defect severity & location.




Figure 1 - Area of investigation shown in green.

The slab within the shaded green area was found to be in a condition appropriate for its age, however there were scattered area of staining and water ingress to the concrete slab, refer photos 1-4. These areas of minor staining were primarily located around pipe penetrations & the area of slab with garden beds above.

A section of slab supporting the front planter box has large vertical cracks along the surface & areas of spalling, refer photo 10

The pool on the ground floor above is supported by a concrete beam on each side, the concrete beam as indicated in figure 1, has sever concrete cancer. Large cracks approx. 3-5mm in width can be seen along the length of the beam, refer photo 17-20

## Discussion

As noted in the introduction, slab pool surround had issue with water drainage, as concrete cancer/ water staining is localised to this area it is likely a result of the water drainage issues.

It is additionally noted that minor concrete cancer was seen at location of carpark exhaust ventilation and around various pipes located around the slab below garden beds/ landscaping above. This indicates that water drainage/ ingress issues may extend to this area on the ground floor & would also need repair to mitigate any further concrete cancer

## Repair Works

Design Sirs recommends checking any drainage pipes/ grates to the ground floor garden/ landscape area to confirm to further water issues.

For concrete cancer repairs, works are classified into 3 categories for defects & repair work, with location & severity shown on plan in Appendix B.

### Defect Classification

Design Sirs classified on-site concrete cancer defects into the following categories:

- Class A:
  - Minor concrete defect and/or staining
  - No reinforcement exposed, minor/ no cracking
- Class B:
  - Moderate visual indication of early concrete cancer
  - concrete cracking/ spalling
  - some (100mm or less) reinforcement showing, some indication of corrosion
- Class C:
  - Severe indication of concrete cancer
  - Concrete cracked and/or fallen away in chunks
  - Moderate reinforcement exposure with significant corrosion.

### Recommended Repairs

- Class A:

Class A repairs may be considered optional, but if not repair will require yearly monitoring

- Scabble back surface concrete until all stained concrete is removed. Up to the depth of reinforcement if necessary
- Any reinforcement that is exposed shall be wired brushed clean of any rust & painted with SikaTop Armatec -110 EpoCem
- Repair concrete with Sika MonoTop -352 NFG concrete repair mortar

- Class B:

- Prop each side of region to be repaired, props shall be spaced at 1.5m centres max.
- Clean area & remove any loose concrete from area.
- Scrabble back/ hammer out 50mm each end along exposed reinforcement min. or until clean reinforcement clean of rust is found
- Confirm extent of corrosion and wire brush clean steel reinforcement
- Paint steel reinforcement in SikaTop Armatec -110 EpoCem
- Repair concrete with Sika MonoTop -352 NFG concrete repair mortar

- Class C:

- Refer Repairs details, Appendix C

We trust this covers the repair requirements. If you have any questions or concerns please don't hesitate to contact the writer directly

**Design Sirs**




**Mark Carroll-Chilts**

Senior Structural Engineer

BEng, MIEAust, NER, RPEQ

# APPENDIX A


## PHOTOGRAPHIC RECORD



**FIGURE 1:** Site Plan: 85 Deakin St. Kangaroo Point - Red outline indicates site, blue indicates focus of investigation



**PHOTOGRAPH 1.:** Defect Class A: Visible staining of concrete, some efflorescence visible



**PHOTOGRAPH 2.:** Defect Class A: Visible staining of concrete, located around pipe penetration



**PHOTOGRAPH 3.:** Defect Class A: Visible staining of concrete, located around air con



**PHOTOGRAPH 4.:** Defect Class A: Staining to concrete around pipe penetrations. Wall also indicates water penetration with notable efflorescence to the block wall



**PHOTOGRAPH 5.:** Defect Class B: Reinforcement exposed due to concrete spalling



**PHOTOGRAPH 6.:** Defect Class B: Reinforcement exposed due to concrete spalling



**PHOTOGRAPH 7.:** Defect Class B: Large area of straining, early stage of steel corrosion



**PHOTOGRAPH 8.:** Defect Class A: Staining & material deposits to concrete around pipe penetration



wall


**PHOTOGRAPH 9.:** Defect Class B: Moderate strain to concrete, large crack at drip tray join



**PHOTOGRAPH 10.:** Defect Class C: large cracks across concrete face, large are of spalling with multiple chunks of concrete falling away to expose aggregate



**PHOTOGRAPH 11.:** Defect Class B: Large area of straining, cracking to concrete surface



**PHOTOGRAPH 12.:** Defect Class B: Large area of straining, cracking to concrete surface



**PHOTOGRAPH 13.:** Defect Class A: Visible staining of concrete, some efflorescence visible



**PHOTOGRAPH 14.:** Defect Class A: Visible staining of concrete, some efflorescence visible, no visible cracking or spalling of concrete



**PHOTOGRAPH 15.:** Defect Class A: Visible staining of concrete, some efflorescence visible around pipe penetration



**PHOTOGRAPH 16.:** Defect Class B: Visible staining of concrete, some efflorescence visible, some spalling of concrete along drip tray



**PHOTOGRAPH 17.:** Defect Class C: Moderate cracking & spalling to concrete beam, beam supports pool above. Cracking depth up to 200mm into depth of beam



**PHOTOGRAPH 18.:** Defect Class C: Previous surface repairs evident



**PHOTOGRAPH 19.:** Defect Class C: Moderate cracking & spalling to concrete beam, beam supports pool above. Cracking depth up to 200mm into depth of beam



**PHOTOGRAPH 20.:** Defect Class C: Previous surface repairs evident

# APPENDIX B

## REPAIR LOCATION PLAN


---



# APPENDIX C

## REPAIR DETAILS


---



- PROP SECTION AS NOTED ON DETAIL, PROPS SHALL BE RATED FOR 100kN EACH (10 TONNE)
- REMOVE EXISTING DRIP TRAY FOR REPAIR WORKS
- SCRABBLE BACK/ HAMMER OUT CONCRETE EACH END OF EXPOSED REINFORCEMENT BAR UNTIL CLEAN STEEL IS FOUND
- WIRE BRUSH CLEAN STEEL REINFORCEMENT  
ANY BARS MISSING OVER 25% OF MASS - CONTACT ENGINEER
- INSTALL SACRIFICIAL ANODE, SIKA FERROGARD -510 PATCH, AT 600 CRS.
  - PRE-DILL HOLE INTO EXG. CONCRETE AT PERIMETER OF REPAIR AREA
  - CLEAR DUST & PRE-WET HOLE FOR 15 MINS.
  - REMOVE EXCESS WATER AND APPLY SIKA FERROGARD -500 CRETE
  - INSTALL FERROGARD 510 PATCH, FULLY EMBED TO 500 CRETE MORTAR
  - FIX ANODE CONDUCTING WIRE TO REPAIRED REINFORCEMENT
- REPAIR CONCRETE WITH SIKA MONOTOP -412 NFG CONCRETE REPAIR MORTAR WITHIN 2 HOURS OF INSTALLING ANODE
- PROPS SHALL REMAIN IN PLACE FOR 7 DAYS
- IF DRIP TRAY IS TO BE RE-INSTATED, CONCRETE SHALL BE TREATED WITH CROMMELIN BLACKSEAL HEAVY DUTY BITUMEN PAINT, FOR A WIDTH OF 500mm, FOR THE FULL LENGTH OF DRIP TRAY

CLASS C REPAIR - AT SLAB FOLD, PHOTO 10  
SCALE 1: 20


|      |                         |          |       |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           |                                                                                                                                |                                                                                                                                                                                                                                                                       |                                                                                 |                          |                |
|------|-------------------------|----------|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------|--------------------------|----------------|
|      |                         |          |       | <br>Structural Consulting Engineers<br>Residential, Commercial & Industrial<br>Investigation & Reporting |  <br>Mobile: 0411 201 605<br>Email: info@designsirs.com.au<br>80 Esther Street, Deagon QLD 4017 | Date: JUN. 24                                                                                                                  | CLIENT<br><br>CORE4 SERVICES                                                                                                                                                                                                                                          | PROJECT<br>CONCRETE CANCER REPAIRS AT 85 DEAKIN STREET, KANGAROO POINT QLD 4169 | PROJECT NO.<br><br>S5466 |                |
|      |                         |          |       |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           | Drawn: D.C.                                                                                                                    |                                                                                                                                                                                                                                                                       |                                                                                 |                          |                |
|      |                         |          |       |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           | Design: M.C.                                                                                                                   |                                                                                                                                                                                                                                                                       |                                                                                 |                          |                |
| 01   | ISSUED FOR CONSTRUCTION | 13/06/24 | D.C.  |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           | Certified: <br>MARK CHILTS<br>RPEQ: Z5483 |  THIS DRAWING & THE STRUCTURAL DESIGN CONTAINED WITHIN REMAINS THE PROPERTY OF DESIGN SIRS AND SHALL NOT BE COPIED, USED OR RETAINED IN PART OR IN WHOLE WITHOUT WRITTEN CONSENT | TITLE<br><br>DETAIL SHEET 1                                                     | DRAWING NO.<br><br>SD1   | REV.<br><br>01 |
| Rev. | Description:            | Date     | Appd. |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           |                                                                                                                                |                                                                                                                                                                                                                                                                       |                                                                                 |                          |                |



CLASS C REPAIR - AT POOL BEAM, PHOTO 17 & 19


SCALE 1: 30

THIS REPAIR METHOD IS ONLY VALID IF BEAM HAS R10 TIES AT 500 CRS. MIN TO BE CONFIRMED PRIOR TO WORKS  
MAIN BEAM REINF. SHALL BE CONFIRMED PRIOR TO WORKS



SECTION A  
SCALE 1:30

- PROP SLAB EACH SIDE OF BEAM AT 1.5m CRS, PROPS SHALL BE RATED FOR 100kN EACH (10 TONNE)
- CALL ENGINEER TO SITE TO CONFIRM EXTENT OF WORKS/ SET OUT OF WORKS
- SCRABBLE BACK/ HAMMER OUT CONCRETE IN THE 2.7m AND 2.5m SECTIONS SHOWN ABOVE FOR A HEIGHT OF 200mm  
REINFORCEMENT IS TO BE FULLY EXPOSED. ALL RUSTED REINF. IS TO BE EXPOSED UNTIL CLEAN STEEL IS FOUND  
ALL CONCRETE IT TO BE LEFT AS A WELL ROUGHENED SURFACE
- WIRE BRUSH CLEAN STEEL REINFORCEMENT  
ANY BARS MISSING OVER 25% OF MASS - CONTACT ENGINEER
- PAINT ALL REINFORCEMENT WITH SIKATOP ARMATEC -110 EPOCEM
- FORM UP BOX AROUNDREPAIR CONCRETE WITH SIKA MONOTOP -412 NFG CONCRETE REPAIR MORTAR
  - RECOMMEND USING FORM BOARDS EACH SIDE OF CONC.
  - SPRAY REPAIR MORTAR UP INTO FORM BOARDS TO INSTALL TO BEAM
  - SCREED BASE OF BEAM TO FINISH
- PROPS SHALL REMAIN IN PLACE FOR 7 DAYS

|      |                         |          |       |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           |               |                              |                                                                                 |                          |              |                                                                                                                                |                                                                                                                                                                                     |                             |                        |                |
|------|-------------------------|----------|-------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------------------------------|---------------------------------------------------------------------------------|--------------------------|--------------|--------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------|----------------|
|      |                         |          |       | <br>Structural Consulting Engineers<br>Residential, Commercial & Industrial<br>Investigation & Reporting |  <br>Mobile: 0411 201 605<br>Email: info@designsirs.com.au<br>80 Esther Street, Deagon QLD 4017 | Date: JUN. 24 | CLIENT<br><br>CORE4 SERVICES | PROJECT<br>CONCRETE CANCER REPAIRS AT 85 DEAKIN STREET, KANGAROO POINT QLD 4169 | PROJECT NO.<br><br>S5466 |              |                                                                                                                                |                                                                                                                                                                                     |                             |                        |                |
|      |                         |          |       |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           | Drawn: D.C.   |                              |                                                                                 |                          | Design: M.C. | Certified: <br>MARK CHILTS<br>RPEQ: 25483 | (C) THIS DRAWING & THE STRUCTURAL DESIGN CONTAINED WITHIN REMAINS THE PROPERTY OF DESIGN SIRS AND SHALL NOT BE COPIED, USED OR RETAINED IN PART OR IN WHOLE WITHOUT WRITTEN CONSENT | TITLE<br><br>DETAIL SHEET 2 | DRAWING NO.<br><br>SD2 | REV.<br><br>01 |
| 01   | ISSUED FOR CONSTRUCTION | 13/06/24 | D.C.  |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           |               |                              |                                                                                 |                          |              |                                                                                                                                |                                                                                                                                                                                     |                             |                        |                |
| Rev. | Description:            | Date     | Appd. |                                                                                                                                                                                              |                                                                                                                                                                                                                                                                           |               |                              |                                                                                 |                          |              |                                                                                                                                |                                                                                                                                                                                     |                             |                        |                |