

Defect Inspection

Completed by Michael Trott

Photo 1



Photo 1 - Details

Door rubbing on frame causing paint to come off
Plain then paint again

Need to take a second photo?

Yes

Photo 2

Defect Inspection

Completed by Michael Trott



Photo 2 - Details
Need door closer on middle door

Need to take a third photo?
Yes

Photo 3



Photo 3 - Details
All silicone work needs to be done again

Need to take a forth photo?

Defect Inspection

Completed by Michael Trott

Yes

Photo 4



Photo 4 - Details

Middle door needs plaining as is rubbing then needs to be painting again

Need to take a fifth photo?

Yes

Photo 5



Photo 5 - Details

Defect Inspection

Completed by Michael Trott

Two door stops to install

Need to take a sixth photo?
Yes

Photo 6



Photo 6 - Details
Handle or push cap to install on door

Need to take a seventh photo?
No

Photo 7

Photo 7 - Details

Need to take a eighth photo?

Photo 8

Photo 8 - Details

Need to take a ninth photo?

Photo 9

Defect Inspection

Completed by Michael Trott

Photo 9 - Details

Need to take a tenth photo?

Photo 10

Photo 10 - Details

Need to take a eleventh photo?

Photo 11

Photo 11 - Details

Need to take a twelfth photo?

Photo 12

Photo 12 - Details

Need to take a thirteenth photo?

Photo 13

Photo 13 - Details

Need to take a fourteenth photo?

Photo 14

Photo 14 - Details

Need to take a fifteenth photo?

Photo 15

Defect Inspection

Completed by Michael Trott

Photo 15 - Details

Need to take a sixteenth photo?

Photo 16

Photo 16 - Details

Need to take a seventeenth photo?

Photo 17

Photo 17 - Details

Need to take a eighteenth photo?

Photo 18

Photo 18 - Details

Need to take a nineteenth photo?

Photo 19

Photo 19 - Details

Need to take a twentieth photo?

Photo 20

Photo 20 - Details

Did you have any additional findings to notate?

Yes

Defect Inspection

Completed by Michael Trott

Notes about any additional findings

General clean needed

Are you finished?

Yes