



McNab
Level 2, SW1, 32 Cordelia St
South Brisbane , Queensland 4101
P: (07) 3252-6900
F: (07) 3846-7555

Project: C1203 Deception Bay Social Housing
643-651 Deception Bay Road
Deception Bay, Queensland 4508

Inspection: 06.89 Plant Inspection - EWP #8

20/24 Items Inspected	11 Conforming	0 Deficient	5 N/A	4 Neutral
---------------------------------	-------------------------	-----------------------	-----------------	---------------------

Type	Safety Inspection & Review	Status	Open
Trade	Structural Steel	Location	Building 2>Level 4
Spec Section		Created By	Shane Pannell
Linked Drawings			
Description	D&S (Beel Steel) EWP Scissor lift. Sticker #23460		
Attachments	171DAC18-DC0F-49E9-A3AB-CACFEDA7D31D.jpeg , 23FDD7AC-54D6-4D7A-8C67-525B1A049786.jpeg		

Inspection Details

Inspection Date	Oct 4, 2025	Due Date	Jan 2, 2026
Point of Contact		Responsible Contractor	Beel welding
Assignee(s)	Shane Pannell		

Inspection Description

0 Neutral 0 Conforming 0 Deficient 0 N/A

1.1 Plant inspection to be completed prior to use on site. Set due date of inspection for next service or 3 months whichever comes first. Keep inspection open to record ongoing maintenance. Close once removed from site.
Activity: 0 Response Changes, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

No Response

Plant Details

3 Neutral 3 Conforming 0 Deficient 1 N/A

2.1 Plant Description (General full photo of machine)
Activity: 1 Response Change, 0 Attachments, 2 Photos, 0 Comments, 0 Observations

EWP Scissor lift

Shane Pannell (McNab) added 2 photos via mobile on Oct 4, 2025 at 08:01 AM AEST



[7A0097BB-D3E9-4DDD-9BD5-F78AAADF67EF.jpeg](#)



[52402A54-F472-4E31-B77A-3048115A2C3B.jpeg](#)

Shane Pannell (McNab) responded with EWP Scissor lift on Oct 4, 2025 at 08:00 AM AEST

2.2 Plant Owner:

Activity: 0 Response Changes, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

No Response

2.3 Plant Operator: (attach HRWL License or competency here and check 1Breadcrumb induction):Details: WP HRWL-Use of a boom-type elevating work platform where the length of the boom is 11 meters or more RTO - Scissor lift, Boom lift (under 11m) BL, SL, Scissor and boom under 11m TBC
- RIHAN301-Operate EWP All operators require familiarization training of the type used.

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Shane Pannell (McNab) responded with TBC on Oct 4, 2025 at 08:02 AM AEST

2.4 Serial No:

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

AG211129-54

Shane Pannell (McNab) responded with AG211129-54 on Oct 4, 2025 at 08:03 AM AEST

2.5 Hours:

Activity: 0 Response Changes, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

No Response

2.6 Plant risk assessment available.

Activity: 3 Response Changes, 0 Attachments, 1 Photo, 0 Comments, 0 Observations



Pass



Fail




N/A

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:05 AM AEST

Shane Pannell (McNab) responded with No Response on Oct 4, 2025 at 08:05 AM AEST

Shane Pannell (McNab) added 1 photo via mobile on Oct 4, 2025 at 08:04 AM AEST

[48675181-0BCE-47BC-9AD1-D55D0FE33ABA.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:04 AM AEST

2.7 Operators' manual readily available (QR code, hard copy, digital etc.)

Activity: 1 Response Change, 0 Attachments, 1 Photo, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) added 1 photo via mobile on Oct 4, 2025 at 08:05 AM AEST



[68D86C07-D9FC-4BB7-9BA2-0C404DD2C338.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:04 AM AEST

2.8 Plant design registration is available for boom type EWP..

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) responded with N/A on Oct 4, 2025 at 08:05 AM AEST

2.9 Where bracket fitted: Fire protection / extinguisher in date. 6 Monthly

Activity: 1 Response Change, 0 Attachments, 1 Photo, 0 Comments, 0 Observations



Pass




Fail



N/A

Shane Pannell (McNab) added 1 photo via mobile on Oct 4, 2025 at 08:05 AM AEST



[D428A052-FE3E-42E2-8F01-F58C812DD6D6.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:05 AM AEST

Maintenance

1 Neutral

3 Conforming

0 Deficient

1 N/A

3.1 Date Last Serviced:

Activity: 0 Response Changes, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

No Response

3.2 Next Service Due: Set due date of inspection for projected due date of service:

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

12/11/2025

Shane Pannell (McNab) responded with 12/11/2025 on Oct 4, 2025 at 08:06 AM AEST

3.3 Daily inspection/pre-start of plant completed. (attach photographic evidence)

Details: See logbook

Activity: 1 Response Change, 0 Attachments, 1 Photo, 0 Comments, 0 Observations



Pass




Fail



N/A

Shane Pannell (McNab) added 1 photo via mobile on Oct 4, 2025 at 08:07 AM AEST



[7FF24978-4D63-4F2B-A713-BBD736E16BAF.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:06 AM AEST

3.4 Routine Inspections carried out 3 monthly (attach photographic evidence)

Details: See logbook

Activity: 1 Response Change, 0 Attachments, 1 Photo, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) added 1 photo via mobile on Oct 4, 2025 at 08:07 AM AEST



[AF0C100E-8CAE-4EAF-94BA-4245F5CBC327.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:07 AM AEST

3.5 Periodic Inspections carried out Annually (attach photographic evidence)

Details: See logbook

Activity: 1 Response Change, 0 Attachments, 1 Photo, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) added 1 photo via mobile on Oct 4, 2025 at 08:08 AM AEST



[28E9844E-7503-4658-BEE5-7CB7F09BE369.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:07 AM AEST

3.6 Major Inspections Carried out (attach photographic evidence)

Details: Completed at 10 years and then every 5 years thereafter.

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) responded with N/A on Oct 4, 2025 at 08:08 AM AEST

Physical Inspection

0 Neutral

5 Conforming

0 Deficient

1 N/A

4.1 No visible oil leaks – hydraulic hoses or connections

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:09 AM AEST

4.2 Tyres in satisfactory condition & serviceable use

Activity: 1 Response Change, 0 Attachments, 3 Photos, 0 Comments, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) added 3 photos via mobile on Oct 4, 2025 at 08:09 AM AEST


[7621D564-9749-47E3-8E64-0832116A3EC0.jpeg](#)

[D31808C8-6D22-45F2-9C47-D3196CBF2B84.jpeg](#)

[74296B8E-D676-4E2D-9E63-613A44BD273F.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:09 AM AEST

4.3 Warning signs fitted and visible

Activity: 1 Response Change, 0 Attachments, 3 Photos, 1 Comment, 0 Observations



Pass



Fail



N/A

Shane Pannell (McNab) left a comment on Oct 4, 2025 at 08:10AM AEST

Warning labels on base sides need to be replaced

Shane Pannell (McNab) added 3 photos via mobile on Oct 4, 2025 at 08:10 AM AEST


[4676AF8C-0720-42AC-B5E1-7ACDD045EEE0.jpeg](#)

[A82E65ED-206A-449F-9E14-3A3D3FAAFB01.jpeg](#)



[7D069C5A-112E-4D96-BEB7-74EDFC0FC20D.jpeg](#)

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:09 AM AEST

4.4 Harnesses available for boom lift. Tagged in date on a register.

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

☐

Pass

☐

Fail

☒

N/A

Shane Pannell (McNab) responded with N/A on Oct 4, 2025 at 08:10 AM AEST

4.5 Travel alarm and amber light operational.

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

☒

Pass

☐

Fail

☐

N/A

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:10 AM AEST

4.6 Are there any obvious defects that may prevent safe operation of equipment.

Activity: 1 Response Change, 0 Attachments, 0 Photos, 1 Comment, 0 Observations

☒

Pass

☐

Fail

☐

N/A

Shane Pannell (McNab) left a comment on Oct 4, 2025 at 08:32AM AEST

No obvious defects sited. Stickers at sides of base need replacing.

Shane Pannell (McNab) responded with Pass on Oct 4, 2025 at 08:10 AM AEST

Fire Ant Management

0 Neutral

0 Conforming

0 Deficient

2 N/A

5.1 All equipment cleaned prior to leaving site and soil build up removed

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

☐

Pass

☐

Fail

☒

N/A

Shane Pannell (McNab) responded with N/A on Oct 4, 2025 at 08:10 AM AEST

5.2 Visually free of fire ants with underside of machinery inspected

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

☐

Pass

☐

Fail

☒

N/A

Shane Pannell (McNab) responded with N/A on Oct 4, 2025 at 08:10 AM AEST