


	Hazards
	- over crowding can cause injury to multiple persons and equipment - No warning signs displayed of any hazards, vehicles entering or awareness. - Injury and or loss of life.
Remedies - isolate specific areas for all activities - display signs, isolation, eliminate majority of equipment.	
	- Unsafe work load, incorrect use of equipment. in this instance serious injury. - Multiple persons on a machine specifically for the use of one person. Serious injury, probable death.
Remedies - always use SWL and work within all WHS. - Never neglect safety procedures to 'get the job done' use correct equipment.	