

Job Instruction/Construction Inspection Report

CONSULTANTS

Project: New Pimlico TAFE Development					Job No: STP17-0699
To	Copy	Circulate	Name	Company	Method of Distribution
✓			Andrew Law	Paynter Dixon	Email
	✓		Paul Neary	Paynter Dixon	Email
	✓		File Copy		
Inspected by: Jeffrey White				Date: 04/010/2019	Time: 15:00pm


- | | | |
|--|--|---|
| ☐ Foundations & Footings | ☐ Concrete Slab on Ground | ☐ Structural Steelwork |
| ☐ Suspended Level 1 PT Slab | ☒ CM Blockwork Walls | ☐ Roof Framing |
| ☐ Timber Framing | | |

End of Trip Facility Wall – Breezeway Blocks

Client Reference Number: 84815

STP Drawing References: 84815/CN/S10.02 (revision A)

STP has conducted an inspection of the breezeblock walls (located on the western side of the new block D extension – see attached image) to ensure the wall reinforcement had been installed in accordance with STP consulting engineers' documentation.



STP is satisfied that the wall reinforcement has been installed in accordance with STP drawings and advice

- ☒ Approved to proceed with work ☐ Further inspection required before proceeding

Signature: **Jeffrey White**

TOWNSVILLE

CAIRNS

MACKAY

BRISBANE

TELEPHONE 07 4724 2626

TELEPHONE 07 4031 8777

TELEPHONE 07 4944 1577

TELEPHONE 07 3257 3883