



DILAPIDATION REPORT

PROJECT: JSCQ00423

CLIENT: AARON JUDGE

SUPERINTENDENT: SCOTT GREER

DATE: 13/11/2019

Johns Lyng Insurance
Building Solutions (Victoria) Pty Ltd

1 Williamsons Rd, Doncaster, Vic 3108

P 03 9272 0000 F 03 9272 0022

ABN 70 097 531 769 A Johns Lyng Group Company



MAKESAFE
BUILDERS



RESTORX
SERVICES



EXPRESS
BUILDERS



INSURANCE
BUILDERS



COMMERCIAL
BUILDERS

www.johnslyng.com.au

BUILDING AUSTRALIA

EXECUTIVE SUMMARY

The following report provides a photographic record of the existing condition of the project works site immediately prior to commencement of the construction works to be undertaken pursuant to a building contract entered into between Johns Lyng Group Pty Ltd and Suncorp

The following report is provided to give an existing conditions survey and photographic record of internal road, car park and existing building.

The following photographs are confirmed to have been taken on 13/11/2019

Supporting Photos



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete



Delap cracks to concrete