



Defect List

[My Items \(3\)](#)
[All Items \(59\)](#)
[Recycle Bin \(0\)](#)

More


Export

+


Create

Add Filter

Status



Items By Assignee Company



Loading

Bulk Actions

1 - 59 of 59 Page: 1 < >

☐	#	Title	Status	Action Required...	Assignee Name	Assignee Company	
☐ Edit View	1	Masonry Precast Item M...	Work Required	• Ryan Browne	• Ryan Browne	• KRB Group	
☐ Edit View	2	Masonry Precast Item M...	Work Required	• Ryan Browne	• Ryan Browne	• KRB Group	
☐ Edit View	3	Concrete Imperfection	Work Required	• Shane Blake • Anthony Bryant	• Ben Forgan • Shane Blake • Anthony Bryant	• TK Formbuild • Azfirm • Azfirm	
☐ Edit View	4	Puddle flange replace re...	Closed		• Stephen Marton	• M & M Waterproofing	
☐ Edit View	5	Bulkhead cut out incorrect	Work Required	• Darren Biffin	• Darren Biffin	• Apex Projects	
☐ Edit View	6	Wall tile falls short of Jo...	Work Required	• Hassan Sharify	• Hassan Sharify	• Six Star Tiling	
☐ Edit View	7	Large grills don't cover ...	Closed		• Rick Clarke	• Applied Air Services	
☐ Edit View	8	Paint Touch Up	Initiated	• Ric Henderson			
☐ Edit View	9	119 - remove tile and bri...	Work Required	• Hassan Sharify	• Hassan Sharify	• Six Star Tiling	
☐ Edit View	10	117 - remove tile and bri...	Work Required	• Hassan Sharify	• Hassan Sharify	• Six Star Tiling	
☐ Edit View	11	Level 3 AWC and Clean...	Work Required	• Hassan Sharify	• Hassan Sharify	• Six Star Tiling	
☐ Edit View	12	L2 cleaners - Gaps too la...	Work Required	• Darren Biffin	• Darren Biffin	• Apex Projects	
☐ Edit View	13	L2 cleaners room - falls ...	Work Required	• Hadi Nasiri	• Hadi Nasiri	• Six Star Tiling	
☐ Edit View	14	L2 servery fall / floor wa...	Work Required	• Hadi Nasiri	• Hadi Nasiri	• Six Star Tiling	
☐ Edit View	15	408, Defective bedding - ...	Closed		• Zaki Rasa	• Six Star Tiling	

☐	Edit	View	16	522 requires grind to be...	Closed		• Zaki Rasa	• Six Star Tiling
☐	Edit	View	17	Drummy bedding to roo...	Closed		• Zaki Rasa	• Six Star Tiling
☐	Edit	View	18	5C smoke wall setting a...	Work Required	• Darren Biffin	• Darren Biffin	• Apex Projects
☐	Edit	View	19	Drummy bedding level 4...	Closed		• Zaki Rasa	• Six Star Tiling
☐	Edit	View	20	Drummy bedding to leve...	Closed		• Zaki Rasa	• Six Star Tiling
☐	Edit	View	21	Drummy bedding to leve...	Closed		• Zaki Rasa	• Six Star Tiling
☐	Edit	View	22	Drummy bedding to leve...	Closed		• Zaki Rasa	• Six Star Tiling
☐	Edit	View	23	Flashing Missing	Work Required	• Mitchell Clark	• Mitchell Clark	• Undercover Roofing
☐	Edit	View	24	Incorrect vinyl used - cle...	Work Required	• Rick Davies	• Rick Davies	• Floor Smart
☐	Edit	View	25	Render	Ready for Review	• Ric Henderson	• Brett Weston	• Universal Coatings
☐	Edit	View	26	Support of Electrical Ca...	Work Required	• Josh Hall • Shane Stoner	• Josh Hall • Shane Stoner	• Monteur Group • Monteur Group
☐	Edit	View	27	Pipework Anchors	Work Required	• Mat Rawlins	• Mat Rawlins	• Fire Boar
☐	Edit	View	28	Sprinkler Ceiling Droppers	Work Required	• Mat Rawlins	• Mat Rawlins	• Fire Boar
☐	Edit	View	29	Incorrect Sprinkler	Work Required	• Mat Rawlins	• Mat Rawlins	• Fire Boar
☐	Edit	View	30	Detector vs Supply Air	Work Required	• Mat Rawlins	• Mat Rawlins	• Fire Boar
☐	Edit	View	31	Fire Cabling	Work Required	• Mat Rawlins	• Mat Rawlins	• Fire Boar
☐	Edit	View	32	Fire Pipework	Work Required	• Mat Rawlins	• Mat Rawlins	• Fire Boar
☐	Edit	View	33	Outside Air Flexible Duct	Work Required	• Jeff Mann • Craig Neame	• Jeff Mann • Craig Neame	• Applied Air Services • Applied Air Services
☐	Edit	View	34	Supply Air Flexible Ducts	Work Required	• Craig Neame • Jeff Mann	• Craig Neame • Jeff Mann	• Applied Air Services • Applied Air Services
☐	Edit	View	35	Exhaust Duct Through ...	Work Required	• Jeff Mann • Craig Neame	• Jeff Mann • Craig Neame	• Applied Air Services • Applied Air Services
☐	Edit	View	36	Refrigerant Pipes	Work Required	• Craig Neame	• Jeff Mann • Craig Neame	• Applied Air Services • Applied Air Services
☐	Edit	View	37	A/C Cassette	Work Required	• Jeff Mann • Craig Neame	• Jeff Mann • Craig Neame	• Applied Air Services • Applied Air Services
☐	Edit	View	38	Incorrect cut outs for ex...	Closed		• Rick Clarke	• Applied Air Services
☐	Edit	View	39	Chipped tiles - room 126	Work Required	• Zaki Rasa	• Zaki Rasa	• Six Star Tiling
☐	Edit	View	40	2.1 Air Gap	Work Required	• Ben Stevens • Jason Morris	• Ben Stevens • Jason Morris	• DYFA • DYFA
☐	Edit	View	41	2.2 Mechanical Condens...	Work Required	• Jeff Mann • Ben Stevens • Jason Morris	• Jeff Mann • Ben Stevens • Jason Morris	• Applied Air Services • DYFA • DYFA
☐	Edit	View	42	2.3 Supports to Stack Vents	Work Required	• Ben Stevens • Jason Morris	• Ben Stevens • Jason Morris	• DYFA • DYFA
☐	Edit	View	43	2.4 Separation of Pipework	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA

☐	Edit	View	44	2.5 Pipework through an...	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA
☐	Edit	View	45	2.6 Separation Required	Work Required	• Ben Stevens • Jason Morris	• Ben Stevens • Jason Morris	• DYFA • DYFA
☐	Edit	View	46	2.7 Loose Water Service ...	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA
☐	Edit	View	47	2.8 Hot and Cold Water ...	Work Required	• Ben Stevens • Jason Morris	• Ben Stevens • Jason Morris	• DYFA • DYFA
☐	Edit	View	48	2.9 Additional TMV Sup...	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA
☐	Edit	View	49	2.10 Support to Isolation...	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA
☐	Edit	View	50	2.11 Plumbing Stack Suf...	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA
☐	Edit	View	51	2.12 Cover Plates	Work Required	• Jason Morris • Ben Stevens	• Jason Morris • Ben Stevens	• DYFA • DYFA
☐	Edit	View	52	2.13 No Bare Brass Visible	Work Required	• Ben Stevens • Jason Morris	• Ben Stevens • Jason Morris	• DYFA • DYFA
☐	Edit	View	53	3.1 Identification Stickers	Work Required	• Ben Stevens • Jason Morris	• Ben Stevens • Jason Morris	• DYFA • DYFA
☐	Edit	View	54	Missing rubbers to glazi...	Closed		• Ashley Caldow	• Fitout Glass and Alum
☐	Edit	View	55	Waterproofing to be rem...	Closed		• Clarence Henderson	• M & M Waterproofing
☐	Edit	View	56	S1 room type splashbacks	Work Required	• Zaki Rasa	• Zaki Rasa	• Six Star Tiling
☐	Edit	View	57	Angle trims to splashbacks	Work Required	• Zaki Rasa	• Zaki Rasa	• Six Star Tiling
☐	Edit	View	58	Window Incorrect	Work Required	• Ashley Caldow	• Ashley Caldow	• Fitout Glass and Alum
☐	Edit	View	59	Door frame installed inc...	Work Required	• Darren Biffin	• Darren Biffin	• Apex Projects