

Inspection: Scaffold Inspection #39

38/39 Items Inspected	31 Conforming	1 Deficient	5 N/A	1 Neutral
---------------------------------	-------------------------	-----------------------	-----------------	---------------------

Type Monthly Scaffold Inspections **Status** In Review

Location

Linked Drawings

Description Type and purpose of scaffold? Stretcher stair Access Reason for inspection? 30 day inspection

Attachments [1673910084358.225830_templImage.jpeg](#), [1673910084230.013916_templImage.jpeg](#)

HRWL Number 3308037

Inspection Details

Inspection Date 17 Jan, 2023

Due Date

Responsible Contractor

Assignee(s) Jack Maddison

Inspection Details

1 Neutral 2 Conforming 0 Deficient 0 N/A

1.1 Location/section of Scaffold

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

L02-L04 north/eastern elevation

1.2 Type & Purpose of Scaffold? eg support, access, handrail

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Stretcher Stair access

1.3 Reason for inspection? eg 30 day inspection, wet weather

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

30 day inspection

Scaffold Location

0 Neutral 3 Conforming 0 Deficient 0 N/A

2.1 Has Sufficient public protection been provided?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

2.2 Are there sufficient safeguards against conductive electricity?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

2.3 Is there sufficient control of vehicle movements around scaffold?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

Supporting Structure/Foundations

0 Neutral 2 Conforming 0 Deficient 5 N/A

3.1 Are sole boards fully supported by the foundations?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

N/A

3.2 Are sole boards installed on a level base?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

N/A

3.3 Is any part of the scaffold built from other than the ground?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

N/A

3.4 If scaffold is not build from the ground, select how?

Activity: 0 Response Changes, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

No Response

3.5 Are needles/spurs installed to design?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

N/A

3.6 Are Jacks/U-Heads sitting square on footing or support?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

N/A

3.7 Does the supporting structure have adequate strength?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

3.8 Are there measures in place to strengthen the supporting structure?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

Access

0 Neutral 24 Conforming 1 Deficient 0 N/A

4.1 What type of access is provided and is it installed and secured correctly?

Activity: 2 Response Changes, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Stairs

4.2 Is scaffold set out correctly?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.3 Is structure square and plumb?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.4 Are handrails fitted and secured?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.5 Does the number of lifts conform to design?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.6 Is bracing adequate?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.7 Do all lifts and hop-ups conform to design?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.8 Are all planks/hop-ups in place?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.9 Is each bay complete with all fittings

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.10 Fixed ties/Rakers correctly installed?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.11 Are wall ties used in the scaffolding?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.12 Have ties been installed as per design?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.13 Are working lift heights correct?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.14 Are all kickboards in place and planks secure?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.15 Are all mesh guards in place?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.16 Mesh or Chain & shade - does it screen all live bays and is it secured?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Unimesh

4.17 Are overlapping boards secured as per COP?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.18 Are there any undue live weights or loads on scaffold?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

No

4.19 Are all accesses clear of hazards?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.20 Is there a maximum load display on loading bays?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.21 Are specialised scaffold designs erected according to design and SWMS?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.22 Do all stairs have captive placement?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.23 Is there sufficient signage or barriers to incomplete scaffold?

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Yes

4.24 By signing above you declare that the scaffold inspection has been completed in accordance with the Act, Regulations, Code of Practices, Australian Standards and Cogent Scaffolding Workplan and Designs; and affirm that this inspection conforms with direction.

True


Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

4.25 Has the scaff tag/board been updated?

Yes

Activity: 1 Response Change, 0 Attachments, 0 Photos, 0 Comments, 0 Observations

Inspection Signatures



Jack Maddison signed on 17 Jan, 2023 at 09:02 AM AEST