

Defect Inspection

Completed by Rohini Chatterjee

Photo 1



Photo 1 - Details

Male toilets, access hatch replaced

Need to take a second photo?

Yes

Photo 2

Defect Inspection

Completed by Rohini Chatterjee



Photo 2 - Details

Wall built out, ceiling tiles replaced, soap dispenser, hand towel holders replaced cleaning

Need to take a third photo?

Yes

Photo 3



Photo 3 - Details

Toilet holder, soap dispenser, mirrors, vanities installed

Need to take a forth photo?

Yes

Photo 4

Defect Inspection

Completed by Rohini Chatterjee



Photo 4 - Details
Door vents installed

Need to take a fifth photo?
Yes

Photo 5



Photo 5 - Details
Toilets replaced and toilet roll holders

Need to take a sixth photo?
Yes

Photo 6

Defect Inspection

Completed by Rohini Chatterjee



Photo 6 - Details

Door vent replaced and signage

Need to take a seventh photo?

Yes

Photo 7



Photo 7 - Details

Toilets, toilet roll holders and locks replaced in carpark male toilets

Need to take a eighth photo?

Defect Inspection

Completed by Rohini Chatterjee

Yes

Photo 8



Photo 8 - Details
Door vent installed

Need to take a ninth photo?
Yes

Photo 9



Photo 9 - Details

Defect Inspection

Completed by Rohini Chatterjee

Cleared all rubbish from site

Need to take a tenth photo?

No

Photo 10

Photo 10 - Details

Need to take a eleventh photo?

Photo 11

Photo 11 - Details

Need to take a twelfth photo?

Photo 12

Photo 12 - Details

Need to take a thirteenth photo?

Photo 13

Photo 13 - Details

Need to take a fourteenth photo?

Photo 14

Photo 14 - Details

Need to take a fifteenth photo?

Photo 15

Defect Inspection

Completed by Rohini Chatterjee

Photo 15 - Details

Need to take a sixteenth photo?

Photo 16

Photo 16 - Details

Need to take a seventeenth photo?

Photo 17

Photo 17 - Details

Need to take a eighteenth photo?

Photo 18

Photo 18 - Details

Need to take a nineteenth photo?

Photo 19

Photo 19 - Details

Need to take a twentieth photo?

Photo 20

Photo 20 - Details

Did you have any additional findings to notate?
Yes

Notes about any additional findings

Site supervisor needs to pick up ceiling tiles and leave paint on site from the upper floor

Defect Inspection

Completed by Rohini Chatterjee

The mirrors have not been retained as per drawings. No upper floor mirrors can be found.
Only 2 mirrors from the downstairs are in the storage in the Carpark.

Are you finished?

Yes